



INSTRUCTION BATTERY CHARGER KIT COMPLETE



INSTRUCTION BATTERY CHARGER KIT COMPLETE

Maintenance charge shall be done every 4 month.

Observe!

The cover shall be open while loading by lying on the black distance head, which is placed by the lock of the box (see picture No 2).

This is done by connecting the connector to the 16A CEE socket. The charging shall proceed until the diode on the charger is flashing green (min.2,5 hours). Recommended charging time is however 24 hours.

By exchange of battery set it's important to check that the connector is removed from the socket. When this is done, dismantle the battery connections in the following priority:

1. Cable between charger and plus pole,
2. cable between charger and minus pole
3. then the remaining cables.

When this is finalized put on the pole protections. To connect a new battery package connect the battery's like above, but in reversed order.

Warning for shortcircuit!

